

Butler S2 Firmware V2.0.1527

Firmware update via Patchelor software.

Version Information:

FIX: respond with random timeout to who is there requests - better load ballance in large installations